District 1 1625 N. French Dr. Hobbs NM 88240	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 March 4, 2004 WELL API NO.
District II	OH COMETRIA TION DIVIGION	30-025-28086
1301 W Grand Ave., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Rd. Aztec, NM 87410	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	5. Indicate Type of Lease STATE FEE X
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	, 	6. State Oil & Gas Lease No.
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR USE "APPLICAT PROPOSALS.)	ES AND REPORTSION WEILES LES TO DRILL OR FORM C-TUT) FOR SUCH	7. Lease Name or Unit Agreement Name ONEY
1. Type of Well: Oil Well Gas Well 🔯 O	JUN 2 ∩ 2008	8. Well Number 1
2. Name of Operator LANEXCO,	INC. / HOBBS OCE	9. OGRID Number 13046
3. Address of Operator 1105 WEST KANSAS, JAL, N	M 88252	10. Pool name or Wildcat EUMONT GAS
4. Well Location		
Unit Letter D : 6	feet from the NORTH line and	660 feet from the WEST line
Section 9	Township 19S Range 37E 11. Elevation (Show whether DR, RKB, RT, GR, e	NMPM County LEA
	3693.3 GL tor below-grade tank closures. a form C-144 must be attached	
	Rng Pit type Depth to Groundwate	
	Below-grade Tank Location ULSectT	
feet from theline and		, , , , , , , , , , , , , , , , , , ,
NOTICE OF INTE PERFORM REMEDIAL WORK ☐ F	PLUG AND ABANDON REMEDIAL WO	BSEQUENT REPORT OF:
	MULTIPLE CASING TEST CEMENT JOB	AMPOSSES for plugging of well here only
OTHER:	OTUED:	will be the best of the best of well plugging)
13. Describe proposed or complete		Forms, when were at the 1) Web Page under
or recompletion). SEE RULE 1103. For Multiple Completions:	Attach wellbore diagram of proposed completion
or recompletion. 5/22/08-1	SEE RULE 1103. For Multiple Completions:MIRU. ND Well head. NU BOP. RI	Attach wellbore diagram of proposed completion H with workstring. Tag @ 2700'.
of starting any proposed work) or recompletion. 5/22/08-1 Circ. plugging mud. Spot 25 sxs	MIRU. ND Well head. NU BOP. RI from 2700' to 2459'. Combining	Attach wellbore diagram of proposed completion H with workstring. Tag @ 2700'. 2 plugs. POH. WOC. SDFD.
or recompletion. 5/22/08-1 Circ. plugging mud. Spot 25 sxs 5/23/08-Spot 25 sxs @ 1550'. POI	MIRU. ND Well head. NU BOP. RI from 2700' to 2459'. Combining to H to 450'. Circ. 50 sxs to surface	Attach wellbore diagram of proposed completion H with workstring. Tag @ 2700'. 2 plugs. POH. WOC. SDFD. ce. ND Wellhead. ND BOP. RDPU.
or recompletion. 5/22/08-1 Circ. plugging mud. Spot 25 sxs 5/23/08-Spot 25 sxs @ 1550'. POl Cut off wellhead. Cut off anchor I hereby certify that the information abo	MIRU. ND Well head. NU BOP. RI from 2700' to 2459'. Combining the to 450'. Circ. 50 sxs to surfaces. Install dryhole marker. Level ove is true and complete to the best of my knowledge.	Attach wellbore diagram of proposed completion H with workstring. Tag @ 2700'. 2 plugs. POH. WOC. SDFD. ce. ND Wellhead. ND BOP. RDPU. el location.
or recompletion. 5/22/08-1 Circ. plugging mud. Spot 25 sxs 5/23/08-Spot 25 sxs @ 1550'. POl Cut off wellhead. Cut off anchor I hereby certify that the information abo	MIRU. ND Well head. NU BOP. RI from 2700' to 2459'. Combining the H to 450'. Circ. 50 sxs to surfaces. Install dryhole marker. Leve	Attach wellbore diagram of proposed completion H with workstring. Tag @ 2700'. 2 plugs. POH. WOC. SDFD. ce. ND Wellhead. ND BOP. RDPU. el location. dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
or recompletion. 5/22/08-1 Circ. plugging mud. Spot 25 sxs 5/23/08-Spot 25 sxs @ 1550'. POI Cut off wellhead. Cut off anchor Thereby certify that the information abore grade tank has been/will be constructed or closs	MIRU. ND Well head. NU BOP. RI from 2700' to 2459'. Combining the to 450'. Circ. 50 sxs to surfaces. Install dryhole marker. Level ove is true and complete to the best of my knowle sed according to NMOCD guidelines , a general permit	Attach wellbore diagram of proposed completion H with workstring. Tag @ 2700'. 2 plugs. POH. WOC. SDFD. ce. ND Wellhead. ND BOP. RDPU. el location. dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan UPT. DATE 6/16/08
or recompletion. 5/22/08-1 Circ. plugging mud. Spot 25 sxs 5/23/08-Spot 25 sxs @ 1550'. POR Cut off wellhead. Cut off anchor I hereby certify that the information abore grade tank has been/will be constructed or closs SIGNATURE	MIRU. ND Well head. NU BOP. RI from 2700' to 2459'. Combining the to 450'. Circ. 50 sxs to surfaces. Install dryhole marker. Level ove is true and complete to the best of my knowled sed according to NMOCD guidelines. In a general permit	Attach wellbore diagram of proposed completion H with workstring. Tag @ 2700'. 2 plugs. POH. WOC. SDFD. ce. ND Wellhead. ND BOP. RDPU. el location. dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan UPT. DATE 6/16/08 Telephone No. 505-395-3056

MAYO MARRS CASING PULLING INC.

Company:

LANEXCO

FAX:

505-748-4585

Lease: Project: ONEY#1

PUSHER:

FRANK \$0.00

ATTN:

P&A CHARLIE MANN BID: Tracking #:

08-5789-1

5/22/2008

8 HRS

SAFETY MEETING - MOVE IN ALL EQUIPMENT - RU - ND WELLHEAD - NU BOP - RIH WITH MMCPI WORKSTRING - TAG @ 2700' - CIRCULATE PLUGGING MUD - SPOT 25 SACKS - FROM 2700' TO 2459' COMBINING 2 PLUGS - POH - WOC - SDFD - POH - SDFD

8	Double derrick rig with 4 man work crew/hr	\$275.00	\$2,200.00
1	PUSHER /DAY	\$300.00	\$300.00
3	CREW TRAVEL TIME	\$150 00	\$450.00
1	Water truck priced per load BRINE (Stays on location)	\$500.00	\$500.00
1	Water truck priced per load FRESH (Stays on location)	\$300.00	\$300.00
1	Pump Truck 5 Day Initial Charge	\$2,500.00	\$2,500.00
1	Steel Pits per well	\$750.00	\$750.00
1	B O P for 2 3/8" and 2 7/8" 5 Day Initial Charge	\$550.00	\$550. 00
25	Cement per sack (CLASS C)	\$14.50	\$362.5 0
24	Salt gel per sack (50# SACK)	\$13.00	\$312.00
2700	2 3/8" Work String/ft	\$0.20	\$540.00

Total Daily Cost =

\$8,764.50