

Form 3160-3  
 (February 2005)

UNITED STATES  
 DEPARTMENT OF THE INTERIOR  
 BUREAU OF LAND MANAGEMENT

FORM 3160-3 (VFD)  
 OMB No. 1004-0137  
 Expires: March 31, 2007

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.  
 NM 01480

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

7. If Unit of CA/Agreement, Name and/or No.

1. Type of Well  
 Oil Well     Gas Well     Other

8. Well Name and No.  
 RENO FEDERAL #002

2. Name of Operator  
 STATE OF NM, FORMERLY RW OIL CO.

9. API Well No.  
 30-005-10151

3a. Address  
 1625 N. FRENCH DRIVE  
 HOBBS, NM 88240

3b. Phone No (include area code)

10. Field and Pool or Exploratory Area  
 Caprock Queen

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
 UNIT LETTER M, SEC 3, T15S, R31E, 800 FWL, 330 FWL, LEA COUNTY, NM

*Chaves*

11. Country or Parish, State  
 LEA COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recombine	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

SSEE ATTACHMENTS

**RECEIVED**  
 FEB 11 2009  
 HOBBSOCD

14. I hereby certify that the foregoing is true and correct.  
 Name (Printed/Typed) *Mark Hoskins* Title *Agent*  
 Signature *Mark Hoskins* Date *10/23/08*

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by *[Signature]* DISTRICT 1 SUPERVISOR Title *[Signature]* Date FEB 11 2009

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

MAYO MARRS CASING PULLING INC.  
BOX 863  
KERMIT, TEXAS 79745

NM0CD

Lease: RW OIL CO. RENO FEDERAL # 2  
Project: P & A

10/10/2008

CIBP @ 3100' - WITH 25 SACKS ON TOP  
PERF @ 1390' - HELD - SPOT 25 SACKS @ 1440' - TAG @ 1100'

10/13/2008

PERF @ 420' - SPOT 25 SACKS - TAG @ 300'  
CIRCULATE 50 SACKS FROM 150' TO SURFACE IN AND OUT OF CASING

PUMPED PLUGGING MUD BETWEEN ALL PLUGS  
INSTALLED DRY HOLE MARKER