

LEA FISHING TOOLS, INC.

BOX ~~1526~~ 1526 PHONE EX 3-2415
HOBBS, NEW MEXICO

11-6-73

MAKE 2 RUNS WITH OVERSHOT & RECOVER SMALL PIECE OF TUBING
EACH RUN. RUN BOWEN JUNK BASKET ON 30' JT. WASHPIPE. MILL ON
JUNK. SHUT WELL IN FOR NIGHT.

11-7-73

RUN NEW SHOE, MILL TILL WASHPIPE JAMMED. RECOVERED 3' TUBING
IN "T" DOG OVERSHOT. RUN NEW SHOE & 1 JT. WASHPIPE.
SHUT DOWN FOR NIGHT.

11-8-73

MILL OVER FISH FROM 1878 1888'. PULL OUT HOLE RUN OVERSHOT
& RECOVER 18' OF FISH. TOP FISH NOW 1906'.

11-9-73

PISK UP NEW SHOE & 4 JOINTS WASHPIPE. MILL & JAM FISH IN PIPE
PULL OUT OF HOLE & RECOVER PIPE & ASSORTED JUNK. RUN NEW SHOE
& RIG UP REVERSE RIG. SHUT DOWNE FOR NIGHT.

11-10-73

MILL TO 1947 JAM WASHPIPE. PULL OUT OF HOLE. REMOVE JUNK
FROM WASHPIPE & RUN BASK INTO HOLE. SHUT WELL IN FOR NIHT.

11-11-73

MILL TILL 1:30 P.M. TOP FISH 1930'. PULL OUT OF HOLE RUN
OVERSHTOT. PULL & JAR ON FISH. SHUT WELL IN FOR NIGHT.