				0 1
DISTRIBUTION	<u> </u>			Supersedes Old C-102 and C-103
SANTA FE	NEW	MEXICO OIL CONSERV	ATION COMMISSION	Effective 1-1-65
FILE				
U.S.G.S.				5a. Indicate Type of Lease
LAND OFFICE	 			State Fee.
OPERATOR				5. State Oil & Gas Lease No.
SU (DO NOT USE THIS FORM FE	NDRY NOTICES A	AND REPORTS ON WELL OR TO DEEPEN OR PLUG BACK T " (FORM C-101) FOR SUCH PRO	LS D A DIFFERENT RESERVOIR.	
l. OIL GAS WELL WELL	OTHER-			7. Unit Agreement Name
duli of peterporation	·			8. Farm or Lease Name N. L. Vinson
Box 670, Hebbs, New	Mexico 88240			9. Well No.
4. Location of Well	1980	Nerth	198 0	10. Field and Pool, or Wildcat
UNIT LETTER	•	-		Grossroads Devonian
Rest	22	9-8	36-E	
THE LINE, S	SECTION	TOWNSHIP	RANGE	имем. ()
	15. El	levation (Show whether DF, F		12, County
		(4)つじ	' DF	Lea
PERFORM REMEDIAL WORK	1	PLUG AND ABANDON REM	EDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON PULL OR ALTER CASING	c	CHANGE PLANS CAS	MENCE DRILLING OPNS.	PLUG AND ABANDONMENT
OTHER 17. Describe Proposed or Complet work) SEE RULE 1103.		CHANGE PLANS CAS	or test and cement Job Ther Plugged and Aban	
other 17. Describe Proposed or Complet work) SEE RULE 1103. 12,255' TD. Spotted 50 sack choic with heavy mud. run tubing below 590 sack cement plug from 1150', across 9-5/8" hole marker. Plugge inspection.	ed Operations (Clearly Cut and reco O'. Spotted a m 5533' to 543 shee at 4200' d and abandene	om 12,255' to 11,000 cas overed 5-1/2" cas 25 sack coment plus 33' at base of Sai	Plugged and Aban and give pertinent dates, incl 55', across 5-1/1 ing from 5500'. Ing from 5905' to Andres: 35 sack	doned
other 17. Describe Proposed or Complet work) SEE RULE 1103. 12,255' TD. Spotted 50 sack chole with heavy mud. run tubing below 590 sack cement plug from 4150', across 9-5/8" hole marker. Plugge inspection.	ed Operations (Clearly Cut and reco O'. Spotted a m 5533' to 513 shee at 1200' d and abandene	om 12,255' to 11,000 cas: State all pertinent details, of the control of the con	Plugged and Aban Plugged and Aban Ind give pertinent dates, incl 155', across 5-1/1 Ing from 5500'. Ing from 5905' to 1 Andres; 35 sack Int plug from 50'. Will advise who	doned uding estimated date of starting any proposed and shee at 12,230'. Loaded Hole caved and could not 5805' in the Glerieta; 25 cement plug from 1,250' to
other 17. Describe Proposed or Complet work) SEE RULE 1103. 12,255' TD. Spotted 50 sack chole with heavy mud. run tubing below 590 sack cement plug from 150', across 9-5/8" hole marker. Plugge inspection.	ed Operations (Clearly Cut and reco O'. Spotted and 5533' to 513 shee at 1200' d and abandene	om 12,255' to 11,000 cas: 25 sack coment pl: 33' at base of Sai 2 and 18 sack come 3 de Harch 11, 1971.	Plugged and Aban Plugged and Aban Ind give pertinent dates, incl 155', across 5-1/1 Ing from 5500'. Ing from 5905' to 1 Andres; 35 sack Int plug from 50'. Will advise who	doned uding estimated date of starting any proposed and shee at 12,230'. Loaded Hole caved and could not 5805' in the Glerieta; 25 cement plug from 1,250' to

RECEIVED

MAR 111971

OIL CONSERVATION COMM. HOBBS, N. M.