

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

L CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. V-22
7. Unit Agreement Name
8. Farm or Lease Name State "A"
9. Well No. 2
10. Field and Pool, or Wildcat No. Bagley Permo Penn
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Southern Union Exploration Company
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 755, Hobbs, NM 88241
4. Location of Well UNIT LETTER <u>M</u> <u>520</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>11 S</u> RANGE <u>33 E</u> NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4275 GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Recomplete to Wolfcamp</u> <input checked="" type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to set CIBP @ 9200' & cap with 35' cement.
Perforate Wolfcamp 8540-60 with 2 jet shots per foot. Treat
with 3,000 gallons 15% NEFE acid. Swab test for commercial
production.

Note: If commercial production is obtained, operator will be
changed to Dwight A. Tipton.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Colonel Walker</u>	TITLE <u>Agent</u>	DATE <u>12/18/85</u>
ORIGINAL SIGNED BY JERRY SEDON		
APPROVED BY <u>DISTRICT 1 SUPERVISOR</u>	TITLE _____	DATE <u>DEC 18 1985</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
DEC 18 1985
O.C.D.
HOBBS OFFICE