

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE  
(Other instructions reverse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR AMOCO PRODUCTION COMPANY.	8. FARM OR LEASE NAME MIDWEST H FEDERAL
3. ADDRESS OF OPERATOR BOX 367, ANDREWS, TEXAS 79714	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL x 1980' FWL Sec 25 (Unit N, SE 1/4 SW 1/4)	10. FIELD AND POOL, OR WILDCAT VADA PENN
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4307' D.F.
	12. COUNTY OR PARISH LEA
	13. STATE N.M.

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

## 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

No workover or recompletion possibilities. Propose to P/A as follows:

- Set CIBP @ 9680' & cap w/ 35' Cement.
- Shoot & pull 5 1/2" CSQ from free point. Est TCMt 6840'.
- Spot 100' plug in & out of Stub.
- " " 5390 - 5290 (T-GCOR 5340')
- " " in & out of 8 7/8" CSA 3985.
- Cut & pull 8 7/8" CSQ from free point. (Est TCMt 2875')
- Spot 100' plug in & out of casing stub (8 7/8")
- " 100' plug 2110 - 2010 (T-AMW 2060')
- " 100' " 367 - 267 (11 3/4" CSA 317 w circ)
- " 10sx @ surface & erect P/A marker.

All intervals to be filled w/ 9.5" mud.

Final Cleanup & level location.

AMENDMENT: 1. Additional 25 sx. cement plug required from 8000 to 8150 feet

2. All cement plugs placed through tubing shall be 25 sx. minimum.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

ADMINISTRATIVE ASSISTANT

DATE

JUL 29 1975

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

O+4 - USGS - H

1 - DIV

1 - SUSP

1 - RRY

\*See Instructions on Reverse Side

JUL 30 1975  
Jim Sims  
JULY SIMS  
ADJUTANT DISTRICT ENGINEER