

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p> <p>5. State Oil & Gas Lease No. L-494-1</p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>		<p>7. Unit Agreement Name</p>
<p>2. Name of Operator Hanson Oil Corporation</p>		<p>8. Farm or Lease Name Amoco State</p>
<p>3. Address of Operator P. O. Box 1515, Roswell, New Mexico 88201</p>		<p>9. Well No. #1</p>
<p>4. Location of Well UNIT LETTER H, 766 FEET FROM THE East LINE AND 1874 FEET FROM THE North LINE, SECTION 2 TOWNSHIP 9-S RANGE 33-E NMPM.</p>		<p>10. Field and Pool, or Wildcat Vada Penn</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 4336 GL</p>		<p>12. County Lea</p>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 3-15-79 Set Wireline Bridge Plug @ 4530' - Spotted 4 sx cement - Top cement @ 4495'.
- 3-19-79 Shot off 5½" pipe @ 4088'.
- 3-20-79 Spotted 25 sk plug from 4260-4160' - Spotted 65 sk cmt plug from 4138-3950' - Covered cut-off & bottom of 8-5/8" casing shoe, 50' in 5½" & 50' up into 8-5/8".
- 3-22-79 Shot 8-5/8" pipe @ 675'.
- 3-23-79 Pumped 60 sk cmt plug from 725-614' - Pulled tbg up to 450' & spotted 60 sk plug & tagged plug @ 340'.
- 3-24-79 Spotted 30 sx cmt from 50-0' - Put up Dry Hole Marker - P&A on 3/24/79.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Louise R. Schmitt* TITLE Production Clerk DATE 4/6/79

APPROVED BY *W. J. Schmitt* TITLE OIL & GAS INSPECTOR DATE JAN 13 1980

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 1 1979
OIL CONSERVATION COMM.
ROBES. N. M.