

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-2064	



SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	
2. Name of Operator EXXON CORPORATION	
3. Address of Operator P.O. Box 1600, MIDLAND, TEXAS 79701	
4. Location of Well UNIT LETTER C 660 FEET FROM THE NORTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 2 TOWNSHIP 12-S RANGE 34-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 4160 DF	

7. Unit Agreement Name
8. Farm or Lease Name SOUTH FOUR LAKES UNIT
9. Well No. 5
10. Field and Pool, or Wildcat FOUR LAKES PENN
12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SET DR PLUG IN BAKER MODEL D PI/R AT 9899, CIRCULATED WELL W/200 BBL SALT GEL MUD AND SPOT 20 SX CEMENT PLUG. RAN FREE POINT INDICATOR, 5 1/2" CSG STUCK AT 5165. SHOT 5 1/2 CSG WITH JET CUTTER AT 5125. SPOTTED 40 SX PLUG THRU TBG AT 5128, PULLED TBG TO 4265 AND SHOT 40 SX PLUG. REMOVED BOP, MIXED 10 SX SURFACE PLUG, INSTALLED WELL MARKER AND CLEANED UP LOCATION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED 	TITLE UNIT HEAD	DATE 1-29-73
APPROVED BY 	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		