

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
06-5092	
7. Unit Agreement Name	

8. Farm or Lease Name	
Cabot State	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Wildcat	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator
	Western States Producing Company
3. Address of Operator	
	900 Building of the Southwest Midland, Texas
4. Location of Well	
UNIT LETTER J FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 4 TOWNSHIP 12-S RANGE 34-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
100' in 11" 4175' G.L.	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

PERFORM REMEDIAL WORK <input type="checkbox"/>	TEMPORARILY ABANDON <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
--	--	---	--------------------------------	--	--	--	--------------------------------	--	---

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Est. Starting Date 3-11-69

1. Spot 25 sacks cement plug from 10,080' back to 9730' in 4 1/2" casing.

2. Free point 4 1/2" casing and cut off at approximately 3200'. Spot 35 sacks plug from 3200' back to 3090' in 8 5/8" casing.

3. Free point 8 5/8" casing and cut-off at approximately 2200'. Spot 100 sacks plug from 2200' back to 2100' in 11" hole.

4. Spot 100 sack plug from 412' back to 312' in 13 3/8" casing.

5. Spot 10 sacks plug at surface and set marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>Don C. Bennett</i>	TITLE Chief Engineer	DATE 3/11/69
APPROVED BY <i>Lesh A. Clements</i>	TITLE Oil & Gas Inspector	DATE

CONDITIONS OF APPROVAL, IF ANY:

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

PERFORM REMEDIAL WORK <input type="checkbox"/>	TEMPORARILY ABANDON <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
--	--	---	--------------------------------	--	--	--	--------------------------------	--	---

Spot 25 sacks cement plug from 10,080' back to 9730' in 4 1/2" casing.