

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-24531
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> XX FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-3662
7. Lease Name or Unit Agreement Name Union State
8. Well No. 1
9. Pool name or Wildcat Morton Permo Penn North

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> oil
2. Name of Operator Elk Oil Company
3. Address of Operator P.O. Box 310 Roswell N.M.

4. Well Location Unit Letter <u>N</u> : <u>1650</u> Feet From The <u>West</u> Line and <u>330</u> Feet From The <u>South</u> Line Section <u>25</u> Township <u>14S</u> Range <u>34E</u> NMPM <u>Lea</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4076.5 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-6-1991 Set CIBP @ 9700' and dump 35' cement on top
11-8-1991 Pull 7000'; of 4 1/2" casing
11-8-1991 Spot 35 sxs @ 7050' -6922' tagged
11-8-1991 Spot 35 sxs @ 6000' -5900'
11-8-1991 Spot 40 sxs @ 4550' -4431' tagged
11-12- 91 Pulled 640' of 8 5/8"
11-12- 91 Spot 90 sxs @ 428'-313 tagged
11-12- 91 Spot 40 sxs @ 100' to surface

Install dry hole marker
Hole circulated with 10# mud

Location cleaned and ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joseph J. Kelly TITLE President DATE 11/10/92

TYPE OR PRINT NAME Joseph J. Kelly TELEPHONE NO. 505/623-3190

(This space for State Use)

APPROVED BY Chang W. Hill TITLE OIL & GAS INSPECTOR DATE NOV 17 '92

CONDITIONS OF APPROVAL, IF ANY: