BURTON DIVISION LABORATO

HALLIBURTON COMPANY LOVINGTON, NEW MEXICO TICKET NUMBER: 298269

			DY WAT	ER ANALYSIS	No. W77-947
T .	Hilliard Drilling Company			Date.	11-18-77
1190 Midland National Bank Tower Midland, Texas			er	This report is the property of Halliburton Company and neither it nor any part thereof nor a copy thereof is to be published or disclosed without first securing the express written approval of laboratory management; it may however, be used in the course of regular business operations by any person or concern and employees thereof receiving such report from Halliburton Company.	
Submitted	by			Date Re	ec. 11-18-77
	Phillips State #1		14,081'	Formati	onDevonian
County		Field	Wildcat	Source_	DST #1
County		SAMPLER		MIDDLE OF RECOVERY	TOP OF RECOVERY
Decistivity		0.193 @ 74 ⁰		0.193 @ 74 ⁰ F	1.78 @ 74 ⁰ F
•		1.038			
•	ravity	6.3			
		6,300			*MPL
Calcium (Ca)		Nil			
Magnesium (Mg)		28,500		28,500	2,500
Chlorides (Cl)		3,200			
Sulfates (SO ₄)		2,400			
Bicarbonates (HCO ₃)		Nil			
Soluble Ir	on (Fe)				
•···•					
Pit Samler - Res. @ 74 ⁰ F 0.590			Chlorides, mpl = 6	5,000	
Remarks:					*Milligrams per liter
Kemarks.					
			. ال کید	aubmitted.	
	_	R	espectrully	submitted,	TONI COMPANIV
Analyst:Brewer			HALLIBUR	TON COMPANY	
CC:				Ву	CHEMIST