Orig: & cc: OCC cc: VDA JTR

## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

	REPORT ON OF CASING	RESULT OF TEST SHUT-OFF	x	REPORT ON REPAIRING			
REPORT ON RESULT OF PLUGGING WELL	REPORT ON OPERATION	RECOMPLETION		REPORT ON (Other)	,	<del></del>	
		March 12, 1953			Hobbs,	New ]	Mexieo
Following is a report on the work	done and the results ob	tained under the headi	ing note	d above at the		(Tiace)	
Sinelair Oil & Gas Compa	MY		Ť.a.	Whitman			
(Company or Ope	erator)			(Lease)	. NE	······································	24
(550.4140404	,						•
T. 14 S , R. 37 E , NMPM.,		Pool,	••••••	Teg	***************************************	•••••••	County.
The Dates of this work were as follows:	3-9-53		•	•			
Notice of intention to do the work (was)	(/////of) submitted on	Form C-102 on					19
and approval of the proposed plan (was)			(Cro	ss out incorrect wo	ords)	•	, 13,
	LED ACCOUNT OF W	ODE BOSES ASSESSED	30TT				
	DEED MOODENI OF W	ORA DONE AND RE	POULIS	UBTAINED			
Spudded 3-9-53							
	10 and cemented	with ACC sacks	of c	COMPON GOME	st 2-10-	.52	
Set 13 3/8" 36# casing @ 3							
Set 13 3/8" 36# casing @ 3 Let set 24 hours and teste							n press
Set 13 3/8" 36# casing @ 3							n press
Set 13 3/8" 36# casing @ 3 Let set 24 hours and teste							n press
Set 13 3/8" 36# casing @ 3 Let set 24 hours and teste							n press
Set 13 3/8" 36# casing @ 3 Let set 24 hours and teste							n press
Set 13 3/8" 36# casing @ 3 Let set 24 hours and teste							n press
Set 13 3/8" 36# casing @ 3 Let set 24 hours and tester resumed drilling.	d with 1,000# Pu	mp pressure for	r 30 i	minutes - N			n press
Set 13 3/8" 36# casing @ 3 Let set 24 hours and teste	d with 1,000# Pu		r 30 i	minutes - N	o decre		n press
Set 13 3/8" 36# casing @ 3 Let set 24 hours and testeresumed drilling.  Witnessed by	d with 1,000# Pu	Sinclair Oil &	r 30   Gas (	ninutes - N	o decre	ase i	•••••
Set 13 3/8" 36# casing @ 3 Let set 24 hours and testeresumed drilling.  Witnessed by	d with 1,000# Pu	Sinclair Oil &	Gas (	Company	o decre	ase i	•••••
Set 13 3/8" 36# casing @ 3 Let set 24 hours and testeresumed drilling.  Witnessed by Harold W. S. (Name)	d with 1,000# Pu	Sinclair Oil &	Gas (	Company	o decre	ase i	•••••
Set 13 3/8" 36# casing @ 3 Let set 24 hours and testeresumed drilling.  Witnessed by Harold W. S. (Name)	d with 1,000# Pu	Sinclair Oil & (Company)  I hereby certify to the best of n	Gas (	Company information giveledge.	o decre	ase i	•••••
Set 13 3/8" 36# casing @ 3 Let set 24 hours and testeresumed drilling.  Witnessed by Harold W. S. (Name)	d with 1,000# Pu	Sinclair Oil & (Company)  I hereby certify to the best of no Name	Gas (	Company information giveledge.	Title)	reman	•••••