

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY OFFICE O. C. C.SUBMIT IN TRI  
(Other instructio  
verse side)

COPY TO O. C. C.

Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to plug or plug a well in a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Plug and Abandon	5. LEASE DESIGNATION AND SERIAL NO. LC-063586
2. NAME OF OPERATOR TEXACO Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME NONE
3. ADDRESS OF OPERATOR P. O. Box 728 - Hobbs, N. M.	7. UNIT AGREEMENT NAME NONE
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Well located 330' from the South Line, and 2324' from the West Line of Section 29, T-19-S, R-32-E, Lea County, N. M.	8. FARM OR LEASE NAME S. A. Bowman-Federal
14. PERMIT NO. Regular	9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3541' (D. F.)	10. FIELD AND POOL, OR WILDCAT Lusk, South
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 29, T-19-S, R-32-E
	12. COUNTY OR PARISH Lea
	13. STATE N. M.

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Subject well has been plugged and abandoned as follows:

1. Remove Head, and mud up hole.
2. Spot 30 Sx. Cement plug from 2500' to 2690'.
3. Spot 10 Sx. Cement plug, surface plug, inside 8 5/8" O. D. Casing 0' to 90'.
4. Cleaned location for inspection by the United States Department of The Interior Geological Survey Office, install 4" marker extending 4' above the ground level. Plug and abandon complete 10:00 A. M. March 6, 1966.

18. I hereby certify that the foregoing is true and correct

SIGNED

Dan Gilett

TITLE

Assistant District  
Superintendent

DATE

March 9, 1966

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

MAR 28 1966

\*See Instructions on Reverse Side

J. L. GORDON  
ACTING DISTRICT ENGINEER

UNITED STATES  
DEPARTMENT OF THE INTERIORSUBMIT IN TRIPL  
(Other instructions  
verse side)E-  
re-Form approved.  
Budget Bureau No. 42-R1424.

## GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Include "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC-063586
2. NAME OF OPERATOR TEXACO Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME NONE
3. ADDRESS OF OPERATOR P. O. Box 728 - Hobbs, New Mexico		7. UNIT AGREEMENT NAME NONE
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Well located 330' from the South Line, and 2324' from the West Line of Section 29, T-19-S, R-32-E, Lea County, N. M.		8. FARM OR LEASE NAME S. A. Bowman-Federal
14. PERMIT NO. Regular		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3541' (D. F.)		10. FIELD AND POOL, OR WILDCAT Lusk, South
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 29, T-19-S, R-32-E
		12. COUNTY OR PARISH Lea
		13. STATE N. M.

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

X

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

We propose to plug and abandon subject well as follows:

1. Mud up hole.
2. Spot 30 Sx. Cement plug from 2690' to 2500'.
3. Spot 10 Sx. Cement surface plug inside 8 5/8" O. D. Casing 0' to 90'.
4. Clean the location for inspection as per the United States Department of The Interior Geological Survey regulations, install 4" marker extending 4' above ground level. Plug and abandon to be complete on or about the first day of March, 1966.

18. I hereby certify that the foregoing is true and correct

SIGNED

Dan Gillett

TITLE

Assistant District  
Superintendent

DATE

February 15, 1966

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

\*See Instructions on Reverse Side

