

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
reverse side)E*
re-Form approved.
Budget Bureau No. 42-R1424.
APPROPRIATION AND SERIAL NO.
71-598192

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER <u>Re-entry</u>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR <u>H. N. Sweeney</u>		7. UNIT AGREEMENT NAME
3. ADDRESS OF OPERATOR <u>Post Office Box 1582, Roswell, New Mexico 88201</u>		8. FARM OR LEASE NAME <u>Federal MA "D"</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>860' FNL and 810' FWL of Section 31, Township 17 South Range 33 East.</u>		9. WELL NO. <u>1</u>
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT <u>Corbin ABO</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>4004' DF</u>		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Section 31, T-17S, R-33E, N.H.P.M.</u>
		12. COUNTY OR PARISH <u>Lea</u>
		13. STATE <u>New Mexico</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Nov. 2 -- Re-entered to clean out, perforate upper ABO and acidize.

Nov. 10 -- Cleaned out to 8690'. Set permanent bridge plug at 8630'.

Nov. 11 -- Perforated .4" shots at 8458', 8496 - 98', 8550 - 52', 8580 - 85 - 88',
8600 - 02' from KB.

Intend to plug as follows:

- 1) 25 sack cement plug (221') from 8520' to 8300' to cover above perforations.
- 2) 15 sack cement plug (132') from 4350' to 4218' to cover perms. 4310' - 4320'.
- 3) 15 sack cement plug (132') from 3700' to 3568' to cover perms. 3670' - 3680'.
- 4) 15 sack cement plug (48') from 2183' to 2135' at top 5 1/2" stub.
- 5) 10 sack cement plug (32') at surface with 4 1/2" marker pipe 4' above surface.

18. I hereby certify that the foregoing is true and correct

SIGNED

Charles W. Hicks

TITLE

Agent

DATE

November 30, 1970

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

RECEIVED
APR 10 1970
OIL CONSERVATION COMM.
HOUSTON, TEXAS