

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP
(Other instructions
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

N M 04242

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Cockburn Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Corbin Queen

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

S-33-T-17S-R-33E

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. NAME OF OPERATOR Target Production Company	
3. ADDRESS OF OPERATOR Box 922, Lovington, New Mexico 88260	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310 ft. from South line and 1650 ft. from East line of Sec. 33 NE/4, NW/4, Twp 17S, Range 33E NMPM	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, OR, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well plugged & abandoned as follows:

Circulated hole with mud

Spot 100 sk. plug @ 3072'

Shot 7' csg @ 2172' & pulled

Spot 35 sk. plug @ 2187'

Spot 35 sk. plug @ 1625'

Shot 8-5/8" casing @ 324' and pulled

Spot 100 sk. plug @ 300'

Plac 10 sk. plug @ surface & install dry hole marker

Cleaned & levelled location, ready for inspection.

REAPD 10-7-74

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

President

DATE

10/8/74

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side