Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

LOWIN WLLKOAED	
OMB No. 1004-0135	
Expires November 30, 2000	,
,	

N	M-0442 04242
	If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side					7. If Unit or CA/Agreement, Name and/or No.			
2. Name of Operator							Fed	leral # 3
Southwestern Energy 3a. Address 2350 N. Sam Suite 300, Houston,	Houston Pkwy. E.,	3	b. Phone No. (include 281–618–4739	e area	code)	9. API W 30-025- 10. Field a	-013	•
4. Location of Well (Footage, Sec. 1980' FSL & 1980' FWI Sec. 33-175-33E	•					Corbin 11. County Lea	or Pa	arish, State
12. CHECK AP	PROPRIATE BOX(ES) TO	O IN	DICATE NATU	RE C	OF NOTICE, R	EPORT, O	R O	THER DATA
TYPE OF SUBMISSION			TY	PE O	F ACTION			
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection		Deepen Fracture Treat New Construction Plug and Abandon Plug Back		Production (Start Reclamation Recomplete Temporarily Ab: Water Disposal	,	000	Water Shut-Off Well Integrity Other

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Please see attached procedure.


SEE ATTACHED FOR **CONDITIONS OF APPROVAL**

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)		
Vonnie J. Cermin	Title Drilling / H	Production Analyst
Signature // MALL	Date 11/25/02	
APPROVED THIS SPACE FOR FEDERA	L OR STATE OFFICE	USE
Approved by (ORIG. SGD.) DAVID R. GLASS	Title	Date
Conditions of approval, it are attached 2Approval of this notice does not warracertify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	ent or lease Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Denius Federal No. 3 Corbin Abo Field P&A Procedure

- 1. MIRU rig. NU BOPs. POOH w/ tubing.
- 2. RU EL and RIH w/ gauge ring and junk basket. RIH and set through CIBP at 8000'. Dump 35' cement on top of bridge plug.
- 3. TIH w/ workstring. Tag TOC on bridge plug. Circ well with 9.5# salt gel mud (9.5# brine mixed w/ 25 lbs gel/bbl). POOH.
- 4. RU WL and cut 4-1/2" casing at 2970'. Pull casing. TIH and spot 35 sx cement plug from 2870'-3020'. POOH.
- 5. RU WL and RIH. Tag TOC. Cut 8-5/8" casing at 360'. RD WL. TIH and spot 90 sx cement plug from 259'-410'. POOH.
- 6. RU WL and RIH. Tag TOC. TOOH and RD WL. Spot 45 sx surface plug from 0'-60'.
- 7. Cut casing off 5' below ground level and install dry hole marker.
- 8. RDMO rig.



Revised	PROPOSED COMPLETION				Drawn	WKB
	LEASE:	Denius Federal	WELL:	3		8/7/2002
	LOCATION:	Corbin Abo			Approved	
	COUNTY:	Lea	STATE:	NM		
	PRODUCING FORMATION:	Abo	Formation		Date	
Southwestern Energy Production Company GOPET						