N. M. Off SURS. COMMISSION P. O. BOX 1980

Form Approved.
Budget Bureau No. 42-R1424

DEPARTMENT OF THE INTERIOR 6. IF INDI

5 LEASE Cockburn Fed NM 04242

DEPARTMENT OF THE INTERIOR	COCKDUIN FEG MM 0
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME Cockburn Fed. NM 04242 8. FARM OR LEASE NAME
1. oil gas other S W D	9. WELL NO.
2. NAME OF OPERATOR M & W of Lovington, Inc. 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Corbin Queen
Box 922, Lovington, NM 88260 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA S-34, T-175, R-33, ENMPM
below.) AT SURFACE: 2310' FSL & 336' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 4702'	12. COUNTY OR PARISH 13. STATE Lea New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) DF 4122
REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	
1. Tag up 500' from surface. Clpsd co	
2. Pick up swedge $(4-3/4")$ and attempt	ot to swedge out. No weight unable
3. Rig down and shut in.	RE CAREA II
O. L. Good Cofety Volve: Many and Type	RECEIVED Set @
Subsurface Safety Valve: Manu. and Type	6. 5. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6.

_ TITLE .

President

___ DATE __

DATE _

3/1/83

and Chapler

JUL 2 0 1988