

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals & Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P. O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P. O. Box 2088  
Santa Fe, NM 7504-2088

WELL API NO. <b>30-025-01523</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>B-2229</b>
7. Lease Name or Unit Agreement Name <b>Caprock Maljamar Unit</b>
8. Well No. <b>97</b>
9. Pool name or Wildcat <b>Maljamar Grayburg San Andres</b>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>4179' RT</b>

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> WELL <input type="checkbox"/> OTHER <b>WTW</b>	
2. Name of Operator <b>The Wiser Oil Company</b>	
3. Address of Operator <b>P.O. Box 2568 Hobbs, New Mexico</b>	
4. Well Location Unit Letter <b>L</b> : <b>330</b> Feet From The <b>West</b> Line and <b>1650</b> Feet From The <b>South</b> Line Section <b>27</b> Township <b>17S</b> Range <b>33E</b> NMPM <b>Lea</b> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>4179' RT</b>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <b>Temporary Abandon</b> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/04/01 MIRU Key Well Service. Unset pkr. POH w/2-3/8" IPC tbg.

12/05/01 LD pkr. RIH w/4-3/4" bit, DC's & 2-7/8" work string. Tag @ 4458'.

12/06/01 Drill t/4458'-4595'. Circulate bottoms up. POH w/2-7/8" tbg. LD DC's & 4-3/4" bit.

12/07/01 RIH w/pkr. & 2-7/8" tbg. Set pkr. @ 4399'. RU Cudd Pumping Service. Drop standing valve. Could not pressure up tbg. POH w/2-7/8" tbg. & pkr. RU Hydrostatic Testers. RIH w/pkr. & test 2-7/8" tbg. LD 7 jts. 2-7/8" tbg. Set pkr. @ 4402'. Cudd acidize open hole 4427'-4595' w/3000 gals. 15% NE-FE acid w/3000# rock salt. ATP 3210# @ 5 bpm. MTP 3750# @ 5.2 bpm. Flush w/29 bbls. fresh water. ISDP 2600#. 5 min. 2400#. 10 min. 2200#. 15 min. 2000#. Left well flowing to frac tank on 1/2" choke.

12/10/01 POH w/2-7/8" tbg. & pkr. RIH w/CIBP & 2-7/8" tbg. Set CIBP @ 4402'. Circulate pkr. fluid. Notified OCD of test. Test was not witnessed. Test performed by Nick Jimenez w/Gandy Corporation. Test casing to 500+ PSI. Original chart attached. POH w/2-7/8" tbg. LD tbg. Well is temporarily abandon. RDMO.

Approval of Temporary  
Abandonment Expires 1/28/07

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner TITLE Production Tech II DATE January 15, 2002  
TYPE OR PRINT NAME Mary Jo Turner TELEPHONE NO. (505) 392-9797

(This space for State Use)

**JAN 28 2002**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

