NO. OF COPIES RECEIVED			Form C-103 Supersedes Old
DISTRIBUTION SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION		C-102 and C-103 Effective 1-1-65
FILE		E.C. F. Commostor	Effective 1-1-03
u.s.g.s.			5a. Indicate Type of Lease
LAND OFFICE			State X Fee
OPERATOR			5. State Oil & Gas Lease No. B-2516
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "TAPPLICATION FOR PERMIT —" (BOTTO CONTINUED OF THE PROPOSALS.)			
1. OIL X GAS WELL OTHER-			7. Unit Agreement Name S.E. Maljamar G-SA
2. Name of Operator Cities Service Company			8. Farm or Lease Name Tract 6
3. Address of Operator			9, Well No.
Box 1919, Midland, TX 79702			5
4. Location of Well UNIT LETTER K 1330 FEET FROM THE South LINE AND 1330 FEET FROM			10. Field and Pool, or Wildcat Maljamar (G-SA)
	tion 29 township 17\$		
15. Elevation (Show whether DF, RT, GR, etc.) 4050 GL			12. County Lea
16. Chec	k Appropriate Box To Indicate N	Vature of Notice, Report or Oth	er Data
	INTENTION TO:		REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	L1
OTHER		OTHER	
17. Describe Proposed or Completed	Operations (Clearly state all pertinent deta	ails, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.			and the second s
1. MIRU pulling unit			
	top of liner @ 3838'.	-1	
3. Set cmt retainer on wireline @ 3809' and stab into retainer w/tubing and seal assembly. 4. Squeeze liner and OH (3809'-4320') using 500 sx Class C cement followed by 500 sx			
Class C w/5# sand and 2% CaCl/sx. Dump excess cmt on retainer.			
5. RIH w/6-1/4" RB & 7" CS on tubing and tag cmt on top of retainer. POOH.			
6. RIH w/tubing open-ended to TOC. Spot 125 sx cmt plug from TOC to ± 2400'.			
	on tubing and set @ ± 96	0'. Squeeze csg leak be	tween 961' to 2403'
using 500 sx Class 8. Install swage on 7	s C cmt. POOH. 7" csg and squeeze csg lea	k shove retainer @ 9601	by pumping down
casing w/150 sx Cl	lass C "thick set" w/2% Ca		
2% CaCl. 9. Cut off wellhead,	fill casing to surface wi	th cement and install 4"	dry hole marker.
9. Cut off wellhead, fill casing to surface with cement and install 4" dry hole marker. 10. Clear location. The COMMENT AS PROTECT 24 Parameter of The Republication of The Re			
	160,000		
	$\frac{p_{\mu\nu}}{2} \sim 10^{-3}$	TO THE PROPERTY OF THE	
	(O.E. Arim	SAME.	
18. I hereby certify that the informat	ion above is true and complete to the best of	of my knowledge and belief.	
\sum_{λ}		Dogion Open tire M	27 1000
SIGNED		Region Operations Manage	r June 2/, 1980
Orig. Sign Jerry Sex			France Prices
APPROVED BY Dist 1. St			PATE 111 7 1980

Dist 1, Supv.

CONDITIONS OF APPROVAL, IF ANY: