Form 3160-3

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. Oil Co. P. 1980 Hobbs, NM 88241

HORM APPEOVED
Budget Bureau No. 1004-0135
Expure: March 31, 1993
5. Least Designation and Sureal No.

NMIC 069420

SUBM	7. If Unit or CA, Agreement Designation	
Type of Well Clas Well Wall Cobar		E. Well Name and No.
Name of Coparising LONGS Franciscon dos CFM	OTL OP. # K1462	ONDED FEDERAL #/>
Address and Tolonbour No.	M 88211 (505) 365-6916	300 250 1585 00 5 1 300 251 59400 0 5 1 10. Pade and Pool, or Explanatory Area
Location of Well (Footneye, Sec., T., R., M., or Survey 6 SNSW 185 338	Description)	II. County or Parish, State
6 NESW 185 33	€ 1980'FSL 1980'FWL	LEA COUNTY, NM
CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REP	
TYPE OF SUBMISSION	TYPE OF ACTIO	ON
Motors of Intent	Absolomoest	Chatge of Plans
Subsequent Report	Resomption Plagging Sont	New Construction New Hos-Reutes Fractions
Firel Atmediuspect Notice	Casing Repair Abstracy Opting Cabor <u>AEPATRS</u> TO FLA	Weser Shut-Off Conversion to Injection Dispose Water
Sweride Proposed or Completed Operations (Clearly mass	BACK ON PRODUCTE all parament details, and give portioner detay, including entiment date of our total depths for all markers and mosts pertinent to this wore.)*	ZML Completes or Community or Season and Land are

1991 OCT 10 P 2: 06 RECEIVED

Len Tatto Decrement	10/8/97
(ORIG. SGD.) ALEXIS C. SWOBODA	Dem

fide 18 U.S.C. Bocton 1001, mater to a

10/8/97

TO: BLM

FROM: LOUIS FULTON

RE: 3160-9 #AJM-084-97

- 1. Please see attached copies of previous correspondence regarding change of operator.
- 2. Wells being placed on production delayed due to pulling units being unavailable to perform necessary pump changes and repairs. We've been on two company's waiting lists for over six months (verifiable through Dawson Production Services and CJS / Pinnacle Production Services in Artesia). Hope to have access to necessary equipment in the near future and wells will be back on production.
- 3. PROCEDURE FOR RETURNING WELLS BACK TO PRODUCTION: To our knowledge, the only repairs necessary to return the wells back to production are pump repair / changes. This "procedure" can be completed when a pulling unit is available as referenced in #2 above. Should other problems be found during the pump change process, they will be immediately addressed.

Please call Louis Fulton at (505) 365-6916, (505) 748-2621 or (505) 746-4787 with questions or to get updates.

Thanks.