

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Expires August 31, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

OXY USA INC.

3. ADDRESS OF OPERATOR

P.O. BOX 50250 MIDLAND, TX 79710

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface 2310 FSL 330 FEL

Unit I

14. PERMIT NO. 30-025-01594

300150150400301

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5. LEASE DESIGNATION AND SERIAL NO.
NMLCO29489A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
FEDERAL AH

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

CORBIN YATES

11. SEC. T, R, M, OR BULK AND
SURVEY OR AREA

SEC 9 T18S R33E

12. COUNTY OR TOWNSHIP

LEA

13. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notices, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRAC TURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRAC TURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and five pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

TD - 4305' PBTD - 3464' YATES PERFS - 3417' - 3464'

IT IS PROPOSED TO P&A THIS WELL IN THE FOLLOWING MANNER:

SEE OTHER SIDE:

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

ENGINEERING ADVISOR

DATE 7/2/92

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the
United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Federal AH #5
Plugging Procedure

Casing : 7" @ 1530' cmtd w/ 50 sx TOC est @ 1000'
5 1/2" @ 3417' cmtd w/ 50 sx TOC est @ 2044'
TD: 4305'
PBSD: 3464'
Open Hole: Yates (3417' - 3464')
Salt: Top @ 1600' Base @ 2750'

- 1.) Notify BLM in Hobbs prior to commencing plugging procedure.
- 2.) MIRU pulling unit. TOO H and LD rods and pump. ND WH, NU BOP. TOO H w/ tbg.
- 3.) RU wireline and set CIBP @ 3400'. Dump 4 sx cmt on top of CIBP.
- 4.) TIH w/ tbg open ended and circ hole w/ 9 lb/gal mud laden fluid.
- 5.) PU on tbg to 2800' and spot 15 sx Class C cmt from 2800' to 2655'. TOO H w/ tbg. TAG PLUG.
- 6.) RU wireline and perforate 2 squeeze holes @ 1650'. Tie unto 5 1/2" casing, open bradenhead and establish circulation through squeeze holes. Mix and pump 300 sx Class C cmt down the casing and circulate cement out the bradenhead. DISPLACE CEMENT TO 1400'.
- 6.A) CEMENT TOP 50' OF SURFACE CASING - O.H. ANNULUS.
- 7.) Cut off WH, install dry hole marker, clean up location, and rip and re-seed location.

RECEIVED

JUL 13 1992

WILLIAM H. HARRIS