

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☐ other TA'd

2. NAME OF OPERATOR

Mobitt Producing TX. & N.M. Inc.

3. ADDRESS OF OPERATOR Nine Greenway Plaza,
Suite 2700, Houston, Texas 77046

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' FNL & 660' FEL, S14, T18S, R33E

AT TOP PROD. INTERVAL: Same as surface

AT TOTAL DEPTH: Same as surface

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☒

(other)

SUBSEQUENT REPORT OF:

☐

☐

☐

☐

☐

☐

☐

☐

☒

5. LEASE

USA (LC 063645)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Carper Sivley Federal "A"

9. WELL NO.

8

10. FIELD OR WILDCAT NAME

E. K. Yates 7-Rivers Queen

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 14, T18S, R33E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3947 GR, 3958 DF

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11-21-84 MIRU Mayo Marrs Csg puller NU BOP MI 2-3/8 workstring Marrs perfs 5 1/2 csg w/4 sqz holes @ 3050.

11-26-84 RIH w/Baker 5 1/2" AD-I pkr. on 2-3/8 tbq to 2700, Displ 5 1/2" csg w/80 bbls 10# mud-laden fluid, set 5 1/2" pkr @ 2700 Marrs sqz thru holes @ 3050 w/30x Cls. C neat cmt, final sqz press 800# WOC 3 1/2 hrs, POH w/2-3/8 tbq & pkr, RIH w/1" sinker bar on wireline TOC 2930, Marrs out 5 1/2" csg @ 1872. Procedure changes were recommended by Bob Pitske w/BLM.

11-27-84 Welded 5 1/2" lift sub on 5 1/2" csg, Pick up on 5 1/2" csg; stretch indicated free to 500. Pump down 5 1/2" csg 1 hr, no gain; WIH w/5 1/2" Baker AD-1 pkr to 1500, sqzd 5 1/2" csg stub @ 1872 w/63x Cls. C cmt. Displaced cmt to 1625; sqz press 700#. Closed well in. Job witnessed by Walter Cox w/BLM.

(SEE REVERSE SIDE)

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED W.B. W. TITLE Authorized Agent DATE 12-26-84

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 3-1-89
CONDITIONS OF APPROVAL IF ANY.

gm

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

17. (Cont'd)

11-28-84 Rel pkr, POH w/2-3/8 tbg & pkr. RIH w/1" Sinker Bar & tagged TOC @ 1640, Marrs cut 5½" csg @ 450, POH w/14 jts 5½" csg to 8' piece. RIH w/2-3/8 tbg OE to 450, Circ 130/x C1s C cmt from 450 to surf, POH w/2-3/8 tbg. Cut off 18-5/8 casing head; Inst P&A marker. RD & Rel Marrs Csg Pullers @ 4 PM. Job witnessed by Walter Cox BLM.

NOTE: This well was formerly the E. K. Queen Unit Tr. 1 Well #8.

RECEIVED
MAR 2 1989
GPO: 1979-880-855/884
FBI BBS OFFICE