

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
J.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐
		5. State Oil & Gas Lease No. E-744
OIL WELL ☐ GAS WELL ☐ OTHER- <u>WFW</u>		7. Unit Agreement Name
Name of Operator <u>Mobil Oil Corporation</u>		8. Farm or Lease Name <u>E.K. Queen Unit L. 8</u>
Address of Operator <u>Box 633, Midland, Texas 79701</u>		9. Well No. <u>1</u>
Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1920</u> FEET FROM <u>West</u> THE LINE, SECTION <u>14</u> TOWNSHIP <u>18S</u> RANGE <u>33-E</u> N.M.P.M.		10. Field and Pool, or Wildcat <u>E-K Gate 7 River Queen</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3919.5 CR</u>		12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☒ CHANGE PLANS ☐ OTHER ☐
	REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐
	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug and abandon as per attached recommendation

I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Christine O. Tucker</u>	TITLE <u>Preservation Clerk</u>	DATE <u>2-2-73</u>
APPROVED BY <u>Joe D. Ramey</u> Dist. 1, Supp.	TITLE _____	DATE <u>Feb 8 1973</u>
CONDITIONS OF APPROVAL, IF ANY:		

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: E.K. QUEEN UNIT TRACT 8 Well No. 1
Field: E.K. YATES 7 RIVERS QUEEN
County: LEA State: NEW MEXICO

RECOMMENDED PROCEDURE:

1. Set C.I.B.P. at 4250'± and cap
w/25x cement.

2. Circulate hole to mud using
25 ox gel per 100 bbls. water

3. Cut and pull 5½" casing at
estimated 1600'-1650'.

4. Set 100' cement plug (355x) in
stub of 5½" w/50' above and
below the cut.

If cut should be below 8½" casing seat:
4A. Set 100' cement plug in both 5½" stub
and 8½" shoe.

5. Set 10' cement plug at surface (75x)

6. Erect monument and clear location

Verbally discussed with A. Brown (4565) + J. Haney (NMCC)

E.K. QUEEN Unit Tr-8 Well #1
 E.K. YATES 7 RIVERS QUEEN
 FIELD
 LEA County, New Mexico

P + A. Procedure

Plugs:

1. Set C.I.B.P. @ 4250' and cap w/ 25x cmt.
2. Set 100' cmt. plug (35x) @ stub of 5 1/2" csg.

If lower cut possible:

- 2A. Set 100' cmt. plugs in both the 5 1/2" stub and 8 5/8" oho.
3. Set 10' plug @ surface (75x)

Mud:

Circ. hole to mud w/ 25x gel per 100 bbls water.

1664' - 8 5/8" - 24 #4
 csg set w/ 50 ex
 cmt.

3750' - EST. TOP OF
 CMT. BEHIND 5 1/2" csg. -

PERF. 4276' - 4290'
 (TOTAL - 14 HOLES)

4296' - 5 1/2" - 4 #4 csg
 set w/ 100 ex of cmt.

4309 - P.B.T.D. -

4313 - T.D.

M.B.
 7/5/72