NO. OF COPIES RECEIVED		Form C 102
DISTRIBUTION		Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE	New Mexico die Condentation Commission	Effective 1-1-65
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		
(DO NOT USE THIS FORM USE **.	SUNDRY NOTICES AND REPORTS ON WELLS A FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	
I. OIL GAS		7. Unit Agreement Name
WELL WELL	OTHER- WIW	
2. Name of Cherator		8. Farm or Lease Name
Mobil Oil Corpor	ation	E. K. Queen Unit TR. 7
3. As Iress of Operator		9. Well No.
Three Greenway F	Plaza East - Suite 800; Houston, TX 77046	3
	1/50	10. Field and Pool, or Wildcat
UNIT LETTERE	. 1650 FEET FROM THE NORTH LINE AND 990 FEET FROM	E.K. Yates 7/River Q.
	0/ 10 0 00 0	
THE West LIN	E, SECTION 24 TOWNSHIP 18-S RANGE 33-E NMPM.	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3894 GR	Lea
16.	Check Appropriate Box To Indicate Nature of Notice, Report or Oth	
Nortez	SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
12 Describe Second of Com-		
work) SEE RULE 1103.	oleted Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
1/3//33 /300 ==	1001 ppmp 0 1001 70 ACT PLOG	
	D, 4381 PBTD, Queen 4324-70. MIRU DA&S.	
	TD, 4381 PBTD, Queen 4324-70. SD rain.	POD 1 -1 POU
	TD, 4381 PBTD, Queen 4324-70. Weld in the flg. instle jts 2-3/8 CL the $\&$ pkr, RIH $w/4-3/4$ RB, $5\frac{1}{2}$ scraper to	
	OH, SDFN.	10 4230 Oli 2-778
	EX Drill @ 4238, test tbg 3000 psi, Knox sqz perfs	4324-4370 w/75x H
	300, spot 5x on ret, pull 2 jts, circ hole to mud, pul	
	2840.	· · · · · · · · · · · · · · · · · ·
	CC, 4381 PBTD, Queen 4324-70. Remove BOP, cut off $5\frac{1}{2}$	HD, weld on $5\frac{1}{2}$
	e, ran free pt, free @ 2058, cut $5\frac{1}{2}$ csg w/jet cutter @	
	TD, 4381 PBTD, 4324-70. Pulled 170,000# w/hyd	
	9 48 jts $5\frac{1}{2}$ $14\#$ J55, ran tbg 59 2105, SDFN, prep to sp	
4/21/77 - 4383 T	D, 4381 PBTD, Queen 4324-70. Spot 35x Class H from 2	2105-2000, pull to 1800,
_	Ox plug Class H to 1600, pull to 26, spot 10x plug to	surf, weld on
plate	& marker, rel unit 5 pm 4/20/77.	

spot 90x plug Class H to 1600, pull to 26, spot 10x plug to surf, weld on plate & marker, rel unit 5 pm 4/20/77.

18, Thereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Richard Anderson

TITLE Authorized Agent

OIL & GAS INSTITUTE

DATE

DATE

CONDITIONS OF APPROVAL, IF ANY:

RELIENTED

OIF of the many of anith