

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-07356
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	N. HOBBS (G/SA) UNIT SECTION 19
8. Well No.	111
9. Pool name or Wildcat	HOBBS (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator ALTURA ENERGY LTD.
3. Address of Operator PO BOX 4294 HOUSTON, TX 77210-4294
4. Well Location Unit Corner D : 330 Feet From The N Line and 330 Feet From The WEST Section 19 Township 18-S Range 38-E NMPM LEA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-7-97 MOVE IN RIG UP P & A EQMT.
 10-7-97 SET 7" CIBP AT 3845'
 10-8-97 RIHW/2-3/8 TBG TO 3840' CIRC HOLE W/130 BLS. MLF.
 10-8-97 PUMP 25 SX FROM 3840 TO 3690'
 10-8-97 PUMP 25 SX FROM 2832 TO 2682' TAG AT 2705'.
 10-9-97 PUMP 25 SX FROM 1623 TO 1475'.
 10-9-97 PERF AT 400'
 10-9-97 CIRC HOLE W/110 SX. 7"-7" x 9" TO SURF.
 10-9-97 R - O P & A EQMT. INSTALL DRY HOLE MARKER,

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE SENIOR SUPERVISOR DATE 10/20/97

TYPE OR PRINT NAME JIMMY BAGLEY TELEPHONE NO. _____

(This space for State Use)

APPROVED BY [Signature] TITLE fld Rep DATE 7-31-01

CONDITIONS OF APPROVAL, IF ANY: GWN

