

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fed ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name N. HOBBS (G/SA) UNIT
Name of Operator SHELL WESTERN E&P INC.		8. Farm or Lease Name SECTION 32
Address of Operator P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)		9. Well No. 322
Location of Well UNIT LETTER G 2310 FEET FROM THE NORTH LINE AND 2310 FEET FROM THE EAST LINE, SECTION 32 TOWNSHIP 18S RANGE 38E		10. Field and Pool, or Wholeness HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3637' GR		12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER PB FOR WSO ☒	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull prod equip. Tag fill.
2. CO 5-1/2" lnr from 3911' to 4217'.
3. PB to 4217' w/sand.
4. Tag PBTD. Cap sand w/2 sx (20') cmt.
5. Install prod equip & return well to prod.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE OCTOBER 9, 1987
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR
DATE OCT 15 1987