

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. A-3071
7. Unit Agreement Name
8. Form or Lease Name State 66-30
9. Well No. 2
10. Field and Pool, or Wildcat Goodwin Abo
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - "A" FORM C-101 FOR SUCH PROPOSALS.

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator CONOCO INC.
3. Address of Operator P. O. Box 460, Hobbs, N.M. 88240
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 30 TOWNSHIP 18S RANGE 37E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER open additional pay <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- ① MIRC, POOH w/ pump & rods. CO well to 7450'.
- ② Spot 2 1/2 bbls 10% Acetic acid. Pert from 7274'-78'; 7283'-88'; & 7296'-7300' w/ 2 TSPF.
- ③ Set pkr @ 7125'. Acidize w/ 75 bbls 15% HCL-NE-FE and flush w/ 30 bbls TFW. Swab.
- ④ Release pkr and reset @ 7200'.
- ⑤ Hang well on and place well on test. Rig down

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE Administrative Supervisor DATE 8-21-86

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE **AUG 27 1986**

RECEIVED
AUG 26 1986
C.C.D.
HOBBS OFFICE