

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION 2040 Pacheco St. Santa Fe, NM 87505

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-23768
5. Indicate Type of Lease STATE [X] FEE []
6. State Oil & Gas Lease No. K-6732
7. Lease Name or Unit Agreement Name Lea Mex State
8. Well No. 2
9. Pool name or Wildcat Vacuum Wolfcamp Northwest
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4097.9

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL [X] GAS WELL [] OTHER []
2. Name of Operator Dinero Operating Company
3. Address of Operator P.O. Box 10505 Midland, TX 79702
4. Well Location Unit Lease J : 2,130 Feet From The East Line and 1980 Feet From The South Line
Section 5 Township 17S Range 34E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK [] PLUG AND ABANDON [] TEMPORARILY ABANDON [] CHANGE PLANS [] PULL OR ALTER CASING [] OTHER []
SUBSEQUENT REPORT OF: REMEDIAL WORK [] ALTERING CASING [] COMMENCE DRILLING OPNS. [] PLUG AND ABANDONMENT [X] CASING TEST AND CEMENT JOB [] OTHER []

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
Plugged with Class "C" Cement
8/19/96 * MIRU
8/20/96 * Set 5-1/2" CIBP @ 10,657'.
8/21/96 * Tag CIBP, circ. well w/M.L.F. spot 25 sxs cmt. 10,657' - 10,405'.
8/22/96 * Cut & Pull 5-1/2" casing from 6010'.
8/23/96 * Circ M.L.F. 6076' to 1800' spot 30 sxs cmt. 6076' - 5935' across 5-1/2" stub. Tag top cement @ 5948'. Spot 40 sxs cmt. 4350' - 3921'.
8/26/96 * Tag top cement @ 4020'. Worked on pulling 8-5/8" casing from 1020'.
8/27/96 * At 1850' Circ M.L.F. spot 30 sxs cmt. 1850' - 1740'. Spot 30 sxs cmt. 1658' to 1548'. Spot 50 sxs cmt 1095' - 970'.
8/28/96 * Tag cmt @ 952'. Circ M.L.F.. Spot 60 sxs 410' - 310'. Tagged @ 300'. Spot 10 sxs 10' - 0'. Weld on plate and dry hold marker, cover pit and cellar. Cut off anchors.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Charlie Williams TITLE Production Superintendent DATE 9/6/96
TYPE OR PRINT NAME Charlie Williams TELEPHONE NO. 915/684-5544

(This space for State Use)
APPROVED BY Johnny Robinson TITLE DATE