

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
B-1040

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name State V "A"
3. Address of Operator Drawer D, Monument, New Mexico 88265	9. Well No. 2
4. Location of well UNIT LETTER <u>L</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>23</u> TOWNSHIP <u>17S</u> RANGE <u>34E</u> NMPM.	10. Field and Pool, or Whidcat Vacuum G/SA
15. Elevation (Show whether DF, RT, GR, etc.) 4028' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/15 to 9/20/82 Pulled & laid down 7/8" & 3/4" rods & pump & tbg. Set CIBP in 5-1/2" csg. @ 4270'. Plugged as follows: 25 bbls. gelled mud below bridge plug, 5 sks. cement plug from 4270' to 4228', 25 sks. cement plug from 2987' to 2736', 25 sks. cement plug from 1700' to 1450' and 15 sks. cement plug from 121' to surface. Gelled mud used to displace each plug of cement. Procedure recommended by Tony Plattsmier w/NMOCD. Removed wellhead and installed dry hole marker. P&A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. J. Fisher TITLE Supv. Admin. Services DATE 9-29-82

APPROVED BY Ronald M. Cothran TITLE OIL & GAS INSPECTOR DATE FEB 9 1983

CONDITIONS OF APPROVAL, IF ANY:

L