Form C-103 State of New Mexico Submit 3 Copies To Appropriate District Energy, Minerals and Natural Resources Office Revised March 25, 1999 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-025-02873 District II OIL CONSERVATION DIVISION 811 South First, Artesia, NM 87210 5. Indicate Type of Lease 2040 South Pacheco District III STATE X FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 2040 South Pacheco, Santa Fe, NM 87505 B-1399-1 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) EAST VACUUM GB/SA UNIT 1. Type of Well: **TRACT 2614** Oil Well Gas Well Other plug and abandon 8. Well No. 2. Name of Operator 001 Phillips Petroleum Company 9. Pool name or Wildcat 3. Address of Operator 4001 Penbrook Street Odessa, TX 79762 VACUUM GRAYBURG/SAN ANDRES 4. Well Location 2310 __ feet from the_ Unit Letter 2310 feet from the SOUTH line and_ line **NMPM** County Section Township 17S Range 35E T.F.A 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3908' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: **ALTERING CASING** PERFORM REMEDIAL WORK PLUG AND ABANDON \mathbf{x} REMEDIAL WORK COMMENCE DRILLING OPNS. PLUG AND **TEMPORARILY ABANDON CHANGE PLANS ABANDONMENT** CASING TEST AND **PULL OR ALTER CASING MULTIPLE CEMENT JOB** COMPLETION OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion THE COMMISSION MUST BE NOTIFIED 24 or recompilation. HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 NOTIFY NMOCD 24 HOURS PRIOR TO INITIATING PLUGGING OPERATIONS. TO BE APPROVED. MIRU PLUG AND ABANDON UNIT. NU PPCO CLASS 1 BOPE. GIH W/ 2-3/8" WS AND TAG CIBP @ 4460'. MIX AND CIRC. WELLBORE WITH 9.5 MUD LADEN FLUID (MLF). PUMP PLUG #1 110 SXS 4460'-2400'. COVERS THE SAN ANDRES, GRAYBURG, QUEEN & YATES. POOH TO 2400'. LD WS. WOC AND TAG PLUG #1. RU TO FREEPOINT 4" LINER. ATTEMPT TO RECOVER 2250 +/-. RU TO FREEPOINT 5-1/2" CASING. ATTEMPT TO RECOVER 2250 +/-. RD CASING RECOVERY EQUIPMENT. TIH WITH WORKSTRING. CURCULATE 9.5# MLF. PUMP PLUG #2 125 SXS 2400'-1600'. COVER THE SALT TOP & SURFACE CASING SHOE. WOC AND TAG. LD WORKSTRING TO 405'. PUMP PLUG #3 WATER BOARD PLUG 75 SXS 405'-3'. ISOLATE WATER BOARD. CUT OFF CASING AND WELLHEADS 3' BELOW GL AND CAP WELL. INSTALL DRY HOLE MARKER. PERFORM RECLAMATION WORK

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE AND LOW TITLE SUPERVISOR, REG./PRORATION DATE 5-24-01

Type or print name L. M. SANDERS Telephone No. (915) 368-1488

(This space for State use)

APPROVED BY Conditions of approval, if any:

_ TITLE_

DATE

m

