

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.O.S. | |
| LAND OFFICE | |
| OPERATOR | |

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL GAS WELL OTHER

2. Name of Operator
JFG Enterprise

3. Address of Operator
701 East Main / P. O. Box 100

4. Location of Well
UNIT LETTER J 2210 FEET FROM THE North of South LINE AND 2310 FEET FROM THE West of East LINE, SECTION 16 TOWNSHIP 20-5S RANGE 32-E NMPM.

7. Unit Agreement Name

8. Firm or Lease Name
Phillips State

9. Well No.
4

10. Field and Pool, or Wildcat
Halfway Yates

15. Elevation (Show whether DF, RT, CR, etc.)

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

| | | | |
|--|---|---|--|
| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | <input checked="" type="checkbox"/> PLUG AND ABANDONMENT |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |
| | | OTHER _____ | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1). Spot 150 sxs cement at 2265 W.O.C. tag at 2186
- 2). Spot 50 sxs cement at 2186 W.O.C. tag at 2067
- 3). Spot 50 sxs cement at 2067 W.O.C. tag at 1818
- 4). Spot 80 sxs cement at 1818 W.O.C. tag at 1427
- 5). Spot 80 sxs cement at 1427 W.O.C. tag at 1055
- 6). Spot 105 sxs cement at 1055 W.O.C. tag at 378
- 7). Spot 80 sxs cement at 378 circulate to surface
- 8). Spot 15 sxs cement at surface to load hole to top set P.A. marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CHEN Raymond Maldonado TITLE Superintendent DATE 9-17-92

APPROVED BY Ray Smith TITLE OIL & GAS INSPECTOR DATE DEC 31 '92

CONDITIONS OF APPROVAL, IF ANY: