

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-070311

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Teas Yates Unit

8. FARM OR LEASE NAME

Tract 8

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Teas Yates

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 13, T20-S, R33-E

12. COUNTY OR PARISH

Lea

13. STATE

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Anadarko Production Company

3. ADDRESS OF OPERATOR

P.O. Box 806, Eunice, NM 88231

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FNL & 990' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3604' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☒

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

Deepen to 3410'

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. RUPU, pulled rods & tubing, 10-19-77;
2. RU reverse unit, clean out, deepen to 3410', 10-22-77;
3. Ran Gama Ray compensated Neutron & Caliper log, 10-23-77;
4. Ran open hole pkr., set at 3356', Acidized open hole section w/1000 gal. 15% NE acid, swab test, 10-24-77;
5. Ran Baker full bore pkr., set at 3160', 10-25-77;
6. Fracture treat all zones w/60,000 gals. 9# gelled brine, 44,000# 20/40 & 40,000# 10/20 sand in 4 stages using 3 stages of rock salt & Benzoic acid flakes; Avg. treating pressure, 2300#, A.I.R., 22 BPM; I.S.D.P., 860#, 10-25-77;
7. Ran tbg., rods & pump, 10-26-77;
8. RDPU, put well pumping, 10-27-77;
9. Well tested 34 BO & 4 BWPD 10-9-77

18. I hereby certify that the foregoing is true and correct

SIGNED Nerb Anderson


TITLE **Area Supervisor**

DATE **11-10-77**

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____



*See Instructions on Reverse Side.

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.