

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
N. M. 753

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Ernest A. Hanson	8. Farm or Lease Name Atlantic State
3. Address of Operator P. O. Box Roswell, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER <u>C</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>16</u> TOWNSHIP <u>20-S</u> RANGE <u>33-E</u> N.M.P.M.	10. Field and Pool, or Wildcat West Teas
15. Elevation (Show whether DF, RT, GR, etc.) 3542' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>REMEDIAL WORK <input checked="" type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>
---	--	--	--

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 12-26-67 Set HOWCO cement retainer plug @ 3210.17'. Squeezed old perforations @ 3219-3223' w/100 sx. Incor + 71 lbs. CFR-2 + 3 cu. ft. salt. Formation squeezed at 3000 lbs. Circulated out excess cement. W.O.C.
- 12-27-67 Waiting on cement.
- 12-28-67 Tested casing at 4000 psi for 30 minutes with no leaks. Perforated 1 - 0.50" jet per foot @ 3171, 3173, 3175, 3178, 3181, 3183.5 & 3185. Fractured with 250 gals. acetic acid + 1000 gals. Spearhead acid + 20,000 gals. lease oil + 20,000 lbs. 20-40 sand. Shut-in well 3 hrs. & commence flowing back load oil.
- 12-29-67 Recovered 125 bbls. load oil & well died. Ran tubing to 3120' and put well on pump.
- 1- 1-68 Recovered all load oil. I.P.P. 58 BOPD.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Henry F. Schward TITLE Exploration Manager DATE Jan. 2, 1968

APPROVED BY _____ DATE JAN 5 1968

CONDITIONS OF APPROVAL, IF ANY: _____

ORIGINAL AND COPIES
SIGNED AND FILED IN THE OFFICE OF THE
ENGINEER DISTRICT No. 1