

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

NM-0250

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

K. F. Quail Federal

9. API Well No.

1

10. Field and Pool, or Exploratory Area

South Lea San Andres

11. County or Parish, State

Lea County, New Mexico

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Armstrong Energy Corporation

3. Address and Telephone No.

P. O. Box 1973, Roswell, New Mexico 88202-1973 623-8726

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**2086' FSL and 556' FWL
Section 1, T20S, R34E**

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4/15/96 Move in, rig up, pull and lay down rods, put on BOP, pull and tally tubing, set cast iron bridge plug 9 5/8 at 5350' on wireline, shut down.

4/16/96 Tag cast iron bridge plug at 5350', circulate hole with salt gel mud, spot 15 sacks cement from 5350' - 5305', pull tubing to 3440', spot 40 sacks from 3440' - 3320', pull tubing to 924', spot 40 sacks from 924' - 804', pull tubing to 60', circulate 20 sacks to surface, shut down.

4/17/96 Cut off wellhead, run 1" tubing to 40' between 9 5/8 X 13 3/8, circulate 15 sacks to surface, put in marker, back fill all pits, cut off deadman anchors, move off.

Class "C" Cement

Approved as to plugging of this well BLM.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed

Title **President**

Date **April 25, 1996**

(This space for Federal or State office use)

Orig. Signed by Shannon J. Shaw

Title **PETROLEUM ENGINEER**

Date **5/8/96**

Approved by _____
Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See instruction on Reverse Side