

WORKOVER PROCEDURE

FEDERAL 11-20-34 NO. 1
1980' FNL & 2130' FWL

Section 11, Township 20 South, Range 34 East
Lea County, New Mexico

The ball sealers used in the breakdowns should be 3/4" diameter, 1.1 S.G. balls. They should be dropped in the acid and the first 70 barrels of slick water at a rate of 1 ball per barrel. Breakdown rates should be as high as possible while staying within the pressure limit of 5700 psi.

If fluid level increases are observed after perforating, swab testing may be desired prior to treating or stimulating.

AMO:bjw
11/30/89

cc: Carrie Baze
Mike Clark
Mickey O'Hare
Floyd Steed
Well File