

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR (Other instructions on reverse side) DATE 03 re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

Oct 4 11 20 AM '90

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR

CARL ROE AREA MANAGERS

3. ADDRESS OF OPERATOR
Parker & Parsley Petroleum Company

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

660' FEL & 1980' FSL, Sec. 15, T-20-S, R-34-E *and I*

14. PERMIT NO

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3658' DF

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

5. LEASE DESIGNATION AND SERIAL NO.

NM 06570

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hanson "A" *Federal*

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lea-Yates

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 15, T20S, R34E

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set CIBP @3400' and dumped 3 sx 14.4 ppg cmt on top. Tagged cmt @3391'.
2. Displaced hole w/9.5# SW gel mud.
3. Set tbg open-ended @3243' and set 1st plug @3242-3142' (10 sx 14.4 ppg cmt.).
4. Set tbg open-ended @1541' and set 2nd plug @1541-1441' (10 sx 14.4 ppg cmt.).
5. Set tbg open-ended @396' and tested 2nd plug to 950 psig, OK. Bill McMannus w/BLM (on location) approved pressure test. Set 3rd plug @396-296' (10 sx 14.4 ppg cmt.).
6. WOC overnight.
7. Tagged 3rd plug @240'.
8. Set surface plug (6 sx 14.4 ppg cmt.) and installed dry hole marker.
9. Reclaimed surface and notified BLM for final inspection 8-9-90.

18. I hereby certify that the foregoing is true and correct

SIGNED

Randy R. Johnson

TITLE

Senior Operations Engr.

DATE

10-3-90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

10-15-90

CONDITIONS OF APPROVAL, IF ANY:

surface reclamation completed

*See Instructions on Reverse Side