

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL.
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 1004-0115
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Parker & Parsley Petroleum Company

3. ADDRESS OF OPERATOR
P. O. Box 3178, Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
660' FEL & 1980' FSL, Sec. 15, T-20-S, R-34-E
Unit I

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3658' DF

5. LEASE DESIGNATION AND SERIAL NO.
NM 06570

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Hanson "A" Federal

9. WELL NO.
1

10. FIELD AND POOL OR WILDCAT
Lea-Yates

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 15, T20S, R34E

12. COUNTY OR PARISH 13. STATE
Lea New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF	PULL OR ALTER CASING
FRACTURE TREAT	MULTIPLE COMPLETE
SHOOT OR ACIDIZE	ABANDON*
REPAIR WELL	CHANGE PLANS
(Other)	

X

SUBSEQUENT REPORT OF:

WATER SHUT OFF	REPAIRING WELL
FRACTURE TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*
(Other)	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Proposed Work:

1. Set CIBP at 3423' (50' A/perfs) & dump 35 feet cmt. (3 sx);
2. Run tbg open-ended to 3400'. Load well with 9.5 ppg mud;
3. Spot 100 ft plug (9 sx) from 3242 to 3142' (B/salt);
4. Spot 100 ft plug from 1541 to 1441' on Rustler;
5. Spot 100 ft plug at base surf. csg, 392-292'; and TAG PLUG.
6. 10 sack plug in surface.
7. Remove WH eqpt & install marker.
8. Reclaim surface, remove any-all surface eqpt.

RECEIVED
JUL 26 10 26 AM '90
CATTLE AREA
COWS

18. I hereby certify that the foregoing is true and correct

SIGNED Lee Yates TITLE Consultant DATE 7-25-90

(This space for Federal or State office use)

APPROVED BY Original by Adm. Division TITLE ? DATE 7-25-90
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side