

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP
(Other instructions
reverse side)TE*
reForm approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC-029519(a)

6. IF INDIAN, ALIEN, OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

B. V. Lynch 'A'

9. WELL NO.

8

10. FIELD AND POOL, OR WILDCAT

Lynch

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 34, T-20-S, R-34-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)1. ON ☐ GAS ☐ WELL ☐ OTHER ☒ Salt Water Disposal

2. NAME OF OPERATOR

TEXACO Inc.

3. ADDRESS OF OPERATOR

P.O. Box 728, Hobbs, New Mexico 88240

4. PURPOSE OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surfaceWell is located 1651' from the South Line and 660' from the
East Line of Section 34, T-20-S, R-34-E, Unit Letter I.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DE, RT, GR, etc.)

3760' DF

16

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐CLEAN WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☒(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. SCOPE, PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.) *

The following work on subject well has been completed:

1. Perforated 5-1/2" casing w/1 JSPF from 3,586' to 3,611' and 3,642' to 3,662'.
2. Acidize perforations w/1,500 gals 15% NE Acid.
3. Returned to Salt Water Disposal.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Assistant District
Superintendent

DATE March 1, 1971

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

MAR 8 1971

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO