

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
MONTICELLO, NEW MEXICO

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-064194

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

8. FARM OR LEASE NAME

William A. & Edward R. Hudson

Federal Hodges

3. ADDRESS OF OPERATOR

9. WELL NO.

P.O. Box 9, Maljamar, New Mexico 88264

1

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

10. FIELD AND POOL, OR WILDCAT

2310' from north and 990' from west lines of Sec. 35-20S-34E

Lynch(Y-SR)

11. SEC., T., E., M., OR BLK. AND SURVEY OR ARMA

Sec. 35-20S-34E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

12. COUNTY OR PARISH

13. STATE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- TEST WATER SHUT-OFF
- FRACTURE TREAT
- SHOOT OR ACIDIZE
- REPAIR WELL
- (Other)
- PULL OR ALTER CASING
- MULTIPLE COMPLETE
- ABANDON*
- CHANGE PLANS

SUBSEQUENT REPORT OF:

- WATER SHUT-OFF
- FRACTURE TREATMENT
- SHOOTING OR ACIDIZING
- (Other)
- REPAIRING WELL
- ALTERING CASING
- ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In reply to your letter 43 CFR3163.1 No. RGD-349-89,

We propose to permanently plug and abandon this well as follows:

Set a "cast iron" bridge plug in 5-1/2" casing at 3650', place 75' cement on top of plug, fill hole with salt gel mud, spot salt cement plug from 3375' to 1600', place 60' cement at surface, install 4" dry hole marker with well data, clean location and reseed according to BLM regulations.

Notify BLM at 887-6544 prior to commencing P & A operations.

RECEIVED
JUL 27 11 41 AM '89

18. I hereby certify that the foregoing is true and correct
SIGNED Lucia Howard TITLE Prod. Supt. DATE 7/26/89

(This space for Federal or State office use)

APPROVED BY Shannon Shaw FOR: CHIEF, LAND RESOURCES DATE 8-15-89
CONDITIONS OF APPROVAL, IF ANY.

*See Instructions on Reverse Side