

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL GAS WELL OTHER

7. Unit Agreement Name
West Pearl Queen Unit

Name of Operator
GULF OIL CORPORATION

8. Farm or Lease Name


Address of Operator
P. O. Box 670, Hobbs, NM 88240

9. Well No.
162

Location of Well
UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM

10. Field and Pool, or Wildcat
Pearl Queen

THE East LINE, SECTION 33 TOWNSHIP 19S RANGE 35E NMPM.



15. Elevation (Show whether DF, RT, GR, etc.)

3695' GL

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

WELL OR ALTER CASING

OTHER

PLUG AND ABANDON

CHANGE PLANS

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

OTHER

ALTERING CASING

PLUG AND ABANDONMENT

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Kill well if necessary with 8.6# GKF. POH with rods & pump. Unseat tubing anchor, POH with tubing & anchor. Set CIBP at 4730'; pressure test casing & CIBP to 500#. Circulate with 8.6# brine water + 0.6% Tretolite KW 37 + 10#/150 bbl Tretolite K 470. ND BOP, NU wellhead. Warehouse rods & pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

BY R D P. H. TITLE Area Engineer DATE 7-16-80

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUL 17 1980