

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL PI NO.	30-025-03291
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-5887

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL GAS WELL OTHER

2. Name of Operator
Pyramid Energy, Inc.

3. Address of Operator
10101 Reunion Place, Ste. 210 San Antonio, TX 78217

7. Lease Name or Unit Agreement Name
East Pearl Queen Unit

8. Well No. 50

9. Pool name or Wildcat
Pearl Queen

4. Well Location
Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line
Section 34 Township 19S Range 35E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

05/28/94 Tagged plug at 4687' and circulated hole with mud. Spotted 25 sacks of cement on top of plug. Located casing leaks from 869' to 1704' with tubing and packer. Obtained plugging instructions from NMOCD. Spotted 100 sacks of cement at 1700'. Squeezed cement into leaks with 9 barrels of water. Waited on cement overnight. Tagged top of cement inside 4 1/2" casing at 1010' with wireline. Perforated 4 1/2" casing with 4 holes at 186'. Pumped 70 sacks of cement down casing through perfs and circulated cement back to surface between 8 5/8" and 4 1/2" casing strings. Left cement inside the 4 1/2" casing from surface to 186'. Cut off wellhead and welded on cap and marker. Well plugged and abandoned.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Scott Graef TITLE Operations Manager DATE 06/20/94

TYPE OR PRINT NAME Scott Graef TELEPHONE NO. (210) 308-8000

(This space for State Use)

APPROVED BY Carly W. Hill TITLE Assistant Manager DATE 06/20/94

CONDITIONS OF APPROVAL, IF ANY:

5