

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-03982

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
R-1858

7. Lease Name or Unit Agreement Name

STATE Y

8. Well No.
1

9. Pool name or Wildcat
Edmont Y-SR-DW

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
MACK ENERGY CORPORATION

3. Address of Operator
P.O. BOX 1359 Artesia, N.M. 88211-1359

4. Well Location
Unit Letter I : 660 Feet From The East Line and 1980 Feet From The South Line

Section 1 Township 19-S Range 26-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) Set 5½ CIBP @ 3850', cap w/35' cement
- (2) Load hole w/mud
- (3) Cut & pull 5½ @ 563'
- (4) Spot 25 sks cement p.ug @ 5½ stub 622', W.O.C. tag cement top @ 497'
- (5) spot 30 sk cement plug @ 8 3/8 shoe @ 333', W.O.C., tag cement top @ 336 cement plug fell down hole, respot cement plug w/30 sks, W.O.C. tag cement top @ 276', cement was inside 8 5/8 casing but not high enough, spot 25 sks cement to bring cement up in 8 5/8 casing higher
- (6) Spot 10 sks cement plug @ surface, Set P&A marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maldonado TITLE Supervisor DATE 8-24-94

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY Johnny Robinson TITLE [Signature] DATE _____

CONDITIONS OF APPROVAL, IF ANY