STATE OF NEW MEXICO ENERGY AND MINEPALS DEPARTMENT

##. #F E#### #EEEFFE#		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
OPERATOR	7	

OIL CONSERVATION DIVISION

DISTRIBUTION	P. O. BOX 2088	Form C-103 Revised 10-1-7
SANTA FE	SANTA FE, NEW MEXICO 87501	
FILE		Sa. Indicate Type of Lease
U.S.O.S.		State X Fon
LAND OFFICE		5. State Oti & Gas Lease No.
SUNDRY LOS THIS FORM FOR PROPOR	NOTICES AND REPORTS ON WELLS SALS TO BRILL ON TO DETPEN ON PLUG BACK TO A DIFFERENT REBER FOR FERMIT -" (FORM C-101) FOR SUCH PROPOSALS.1	evoia.
OIL CAS OTHER. Water Injection		7. Unit Agreement Name Northwest Eumont Unit
2. Name of Operator		8. Form or Lease liame
Gulf Oil Corpora	ation	9. Well No.
P. O. Box 670, Hobbs, NM 88240		103
14. Location of Well	20003, 111 00010	10. Field and Pool, or Wildcat
0 66	60 FEET FROM THE South LINE AND 198	0 Eumont
UNIT LETTER	FEET FROM THE LINE AND TO	
THE East LINE, SCETION	11 TOWNSHIP 19S RANGE 36E	ньры.
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3735' GL	Lea
16. Check Ap	propriate Box To Indicate Nature of Notice, R	eport or Other Data
NOTICE OF INT		UBSEQUENT REPORT OF:
<u></u>		<u> </u>
- PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
- TEMPORARILY ASAHDON	COMMENCE DRILLING OP	PLUG AND ABANDONMENT
PULL OR ALTER CABING	CHANGE PLANS CASING TEST AND CEMEN	
	OTHER TA	
0THER	<u> </u>	·
17. Describe Proposed or Completed Oper	ations (Clearly state all pertinent details, and give pertinent d	ates, including estimated date of starting any propose
work) SEE RULE 1103.		
•		
	and tubing. Set CIBP at 3967', test	
ended tubing.	Displace hole. ND BOP. NU & close in	WH.
		·
•		
•		
		. *
		•
	•	
	and is true and complete to the boat of my burned do and burned.	af .
18. I nereby certify that the information ab	ove is true and complete to the best of my knowledge and beli	T10
(V)	Area Engineer	1-20-83
BIGHED VICE V	Title Med Biglitter	DAYE 12000
ORIGINAL SIGNE	D BY	