

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State Free

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Sun Oil Company 3. Address of Operator P.O. Box 1861, Midland, Texas 79702 4. Location of Well UNIT LETTER <u>M L</u> 661.1 FEET FROM THE <u>West</u> LINE AND 1985.3 FEET FROM THE <u>South</u> LINE, SECTION <u>24</u> TOWNSHIP <u>19S</u> RANGE <u>36E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3688.5 GR 12. County Lea	7. Unit Agreement Name 8. Farm or Lease Name J. L. Barr 9. Well No. 2 10. Field and Pool, or Wildcat Eumont Gas
--	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Blow well down.
2. MIRU. Pull rods and pump install BOP w/stripper.
3. RIH w/2-3/8" tail pipe and Otis pkr, set pkr @ 3600'.
4. Retrieve plug and RDRR. Prepare to acidize.
5. Acidize w/6000 gals 60 quality foamed acid in 3 equal stages.
6. Shut down prepare to blow back, if not obtain swab unit.
7. If necessary RIH w/pump and rods. Produce well on 2" choke.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Accounting Assistant DATE 7 January 1980

APPROVED BY Jerry Sexton TITLE Dist. 1, Supv. DATE Jan 11 1980
CONDITIONS OF APPROVAL, IF ANY: