

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Enr Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-3464
7. Lease Name or Unit Agreement Name New Mexico "F" State
8. Well No. 1
9. Pool name or Wildcat Eunice Monument Grayburg-San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
Texaco Producing Inc.

3. Address of Operator
PO Box 728, Hobbs, New Mexico 88240

4. Well Location
Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line
Section 24 Township 19-S Range 36-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3701' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
- 3-8-89. Pull rods, pump, & tbg. TIH W/6 1/4" bit. Tag @ 3979'. TOH.
 - TIH W/4" casing gun. Perf 6 1/4" OH W/2 JSPI @ 3902, 09, 10, 11, 12, 13, 14, 15, 33, 39, (10 int, 20 holes).
 - Acidize OH W/3000 gal 15% NEFE W/1 drum NL Checkersol mutual solvent.
 - Run production equipment. Pump back load.
 - Squeeze down backside W/220 drums SP-307 barium scale inhibitor in 200 bbls fresh water in 3 stages. Shut-in 48 hrs.
 - On 24 hr OPT ending 9:00 AM 4-5-89. Pump 21 B0, 28 BW, .2 MCFPD, GOR 10, Gravity 32.6° API @ 60°.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James A. Head TITLE Area Superintendent DATE 4-7-89

TYPE OR PRINT NAME James A. Head TELEPHONE NO. 397-3571

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT I SUPERVISOR TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____

APR 13 1989

RECEIVED

APR 12 1988

OCD
HOBBS OFFICE