

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**OIL CONSERVATION DIVISION**

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-04054
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1431-3
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 9
8. Well No.	11
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐ GAS WELL ☐ OTHER INJECTION WELL

2. Name of Operator  
Amerada Hess Corporation

3. Address of Operator  
P.O. DRAWER D, MONUMENT, NM 88265

4. Well Location  
Unit Letter K : 1980 Feet From The SOUTH Line and 1980 Feet From The WEST Line  
Section 25 Township 19S Range 36E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #911 (02-18-97 THRU 02-22-97)

TYLER WELL SVC. & STAR TOOL MIRU. PRESS. TST'D. CSG. TO 560# & CHARTED 30 MIN. TST. ND INJ. TREE & NU BOP. GOT OFF PKR. & BROKE CIRC. RTNS. W/PIECES OF POLYETHYLENE & SCALE. GOT ON & RELEASED PKR. TOH W/TBG., ON-OFF SKIRT & ARROWSET 1-XS PKR. CHG'D. BOP RAMS FR. 2-3/8" TO 2-7/8". TIH W/BIT, BIT SUB, SN & 132 JTS. OF TBG. TAGGED @ 4,045'. LOADED CSG. W/35 BBLS. & BROKE CIRC. CIRC. WELL CLEAN. TOH W/9 JTS. TBG. BIT @ 3,793'. TOH W/123 JTS. TBG., SN, BIT SUB & BIT. TIH W/FTI'S SONIC HAMMER, SN & 132 JTS. TBG. TAGGED @ 4,045'. INSTALLED STRIPPER HEAD. PUMPED 30 BBLS. FW & BROKE CIRC. WASHED OH FR. 3,817'-4,045' IN 4 STAGES. EACH STAGE PUMPED 60 BBLS. @ 3.75 BPM @ 1,300# W/FULL RTNS. TO REVERSE PIT. RCV'D. FORMATION, RUBBER, PLASTIC, & METAL SHAVINGS. CIRC. WELLBORE CLEAN @ 3,823'.  
(CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 02-24-97  
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

ORIGINAL SIGNED BY  
GARY WINK  
FIELD REP. II

APPROVED BY [Signature] TITLE [Signature] DATE FEB 28 1997  
CONDITIONS OF APPROVAL, IF ANY: