

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-2287	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input checked="" type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sun Exploration & Production Company	8. Farm or Lease Name New Mexico State
3. Address of Operator P. O. Box 1861, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM <u>East</u> THE <u>25</u> LINE, SECTION <u>19-S</u> TOWNSHIP <u>36-E</u> RANGE <u>36-E</u> NMPM.	10. Field and Pool, or Wildcat Eunice Monument (G-SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3663' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Acidize</u> <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU PU. POH W/ RODS (66 TAPER, 'K' GRADE) & PUMP (2x1.5x16).
ND WH. NU BOP. PICK-UP EXTRA 1-2 JTS 2-3/8" TBG & TAB PBD ($\pm 3979'$)
TALLY OUT OF HOLE W/2-3/8", 4.7#, J-55 PROD TBG STANDING BACK.
- RIH W/ 4-3/4" RB & 5-1/2" (15.5#) CSG SCRAPER ON 2-7/8", 6.5#, J-55 WS
(OR N-80) TO PBD, POH. IF FILL PRESENT, RIH W/ BULLDOG BAILER ON BIT
& SCRAPER RUN. CLN OUT TO PBD ($\pm 3979'$) IF NECESSARY FOR BAILER TO WORK,
PUMP DOWN BACKSIDE W/ 2% KCL. SEND SAMPLE OF FILL TO PSL.
- MIRU BJ-TITAN. RIH W/ 5-1/2" x 2-7/8" PFT ON 2-7/8" WS TO $\pm 3900'$.
NU STRIPPING HEAD. LOAD TBG W/NE 2% KCL (2 GPT NE-2). CHECK TOOL.
IF ANNULAR FLUID LEVEL INSUFFICIENT FOR TOOL OPERATION, RU TRANSPORT TO
ANNULUS AND PUMP DOWN BACKSIDE @ $\pm 1-2$ BPM OR AS REQUIRED FOR PROPER TOOL
OPERATION. USE NE 2% KCL FRSH WTR. WORK TOOL THRU PERFS (1 FULL ROUND TRIP)
IN CIRC MODE USING NE 2% KCL. SPOT 6000 GALS 20% NEFE HCL W/ADDITIVES* TO
TOOL. CLOSE BACKSIDE IF CIRCULATION PREVIOUSLY ESTABLISHED. STOP PUMPING
DOWN BACKSIDE IF FLUID LEVEL BECOMES SUFFICIENT FOR TOOL OPERATION. DISPLACE
ACID IN TBG & FLUSH BACKSIDE USING NE 2% KCL. RECORD 5, 10 & 15 MIN SIP,
ND STRIPPING HEAD. POH W/ 2-7/8" WS & "PFT" LAYING DOWN.

CONTINUED PAGE 2

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Maria L. Perez</u>	TITLE <u>Accounting Associate</u>	DATE <u>3-3-88</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE <u>MAR 7 - 1988</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
MAR 4 - 1988
OCD
HOBBE OFFICE