

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.  
300250561400

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.  
B-2656

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name  
State A-17

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

8. Well No. 5

2. Name of Operator  
Conoco, Inc.

3. Address of Operator  
10 Desta Dr., Ste 100W, Midland, TX 79705-4500

9. Pool name or Wildcat  
Eumont Yates  
Seven Rivers Queen

4. Well Location  
Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line  
Section 17 Township 19S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
DF 3697'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to temporarily abandon this well by the following procedures:  
1. Clean out to PBTD at 3790'.  
2. RIH with RBP and packer and test casing.  
3. RIH with 5 1/2" cement retainer to 3400' and set it.  
4. Pressure test retainer to 500 psi for 30 minutes and circulate packer fluid.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.  
SIGNATURE Jerry W. Hoover TITLE Sr. Conservation Coordinator DATE 6/14/91  
TYPE OR PRINT NAME Jerry W. Hoover TELEPHONE NO. (915) 686-6548

(This space for State Use)  
APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: