

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-05626
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-6506-1
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 2
8. Well No.	7
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Amerada Hess Corporation
3. Address of Operator P.O. Box 840, Seminole, Texas 79360
4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>18</u> Township <u>19S</u> Range <u>37E</u> NMPM <u>LEA</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK PLUG AND ABANDON

TEMPORARILY ABANDON CHANGE PLANS

PULL OR ALTER CASING

OTHER: CONVERT TO INJECTION WELL.

REMEDIAL WORK ALTERING CASING

COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT

CASING TEST AND CEMENT JOB

OTHER: _____

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #207

Order No. R-9596

Plan to:

INSTALL TEST ANCHORS. MIRU PULLING UNIT. MIRU REVERSE UNIT. SET TANKS. CIRC. KILL FLUIDS AS REQUIRED. NU BOP. TOH W/PROD. EQUIPMENT LAYING DWN. RODS. CIRC. KILL FLUIDS AS REQUIRED. TOH W/2-3/8" TBG. PU & TIH W/4-3/4" BIT & TBG. TAG TD @ 4,030'. CIRC. BOTTOMS UP. TOH W/TBG. & BIT. TIH W/RBP ON TBG. SET RBP @ +/-3,750'. CIRC. WELL W/WATER. TST. CSG. TO 700 PSIG. TOH W/TBG. ND BOP'S. ND OLD WELLHEAD. INSTALL 7-5/8" SOW X 7-1/16" 3M CASING SPOOL (5-1/2" SLIPS). INSTALL 7-1/16" 3M TBG. SPOOL. NU BOP'S. TIH W/TBG. & ON-OFF TOOL. LATCH RBP & UNSET. TOH W/TBG. & RBP. TIH W/TBG. O.E. SPOT CMT. PLUG FR. 4,030'-3,970'. TOH W/TBG. SI WOC. TIH W/4-3/4" BIT & TBG. TAG TOC @ 3,970'. SWAB WELL TO CONFIRM NO SAN ANDRES COMMUNICATION. TOH W/TBG. & BIT. MIRU WIRELINE. STRING SHOOT O.H. FR. 3,874'-3,970' (CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: Terry L. Harvey TITLE: SR. STAFF ASSISTANT DATE: 06-04-97
TYPE OR PRINT NAME: TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY