

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
**B-2656**

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEW OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - II (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL  GAS WELL  OTHER

7. Unit Agreement Name

Name of Operator  
**CONOCO INC.**

8. Farm or Lease Name  
**State AC Com**

Address of Operator  
**P. O. Box 460, Hobbs, N.M. 88240**

9. Well No.  
**1**

Location of Well  
UNIT LETTER **L** **1980** FEET FROM THE **South** LINE AND **660** FEET FROM

10. Field and Pool, or Wildcat  
**Eumont Queen Gas**

THE **West** LINE, SECTION **19** TOWNSHIP **19-S** RANGE **37-E** N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

10. County  
**Lea**

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK   
TEMPORARILY ABANDON   
PULL OR ALTER CASING

PLUG AND ABANDON   
CHANGE PLANS

REMEDIAL WORK   
COMMENCE DRILLING OPNS.   
CASING TEST AND CEMENT JOB   
OTHER \_\_\_\_\_

ALTERING CASING   
PLUG AND ABANDONMENT

OTHER **repair csg**

17. Description of Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**MIRU. Kill well w/TFW. POOH w/tbg, seat nipple, mud anchor. GIH w/workstring, retrievable bridge plug, treating pkr. Test csg. Establish circulation. Set RBP 50' below hole. Spot 1sx sand on RBP. POOH w/workstring and pkr. GIH w/workstring and cmt. retainer. Set retainer 50' above hole. Contact Division Engineering Office for volume of cmt to be circ. Spot 5 sx on retainer. POOH. WOC 12hrs. GIH, drill cut cmt plug and retainer. Circ. sand off RBP. POOH. GIH w/pkr. workstring and RBP retrieval tool. Test cmt job. POOH. GIH and run CNL-GR collar locator. Log 3967'-2700'. Run tbg, seat nipple, & mud anchor. Return well to production.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **W.A. Butterfield**

TITLE **Administrative Supervisor**

DATE **October 22, 1980**

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: